

BIC K2500 Series Backhoe Auxiliary Hydraulics

(Trouble shooting electrical system)

If system operates with solenoid manual override (red button) but not with switch check items on this diagram.

